

Studer A820/7MCH Firmware Revised 4June2014

Parallel Ch. Control IF 1.820.787.26 IC 18 27128

1.820.984 .20 20/87  
.21 21/87  
.22 41/87  
.23 22/88 18(C4A2)  
.24 02/91  
.25 02/91 same as .24, improved reset performance

MPU Tape Deck 1.820.781.31 IC 16 & 18 27128

1.820.985 .20 06/88  
.21 22/88  
.22 35/88 16(06E9) 18(3F7F)  
.23 20/89 16(7122) 18(99AF)  
.24 37/89 16(0951) 18(844E)  
.25 48/89  
.26 16/91 16(CD6B) 18(4407)  
.27  
.28 91/10/08 same as .27, improved reset performance  
.29 50/92 16(9C0F) 18(75EC)  
.30 35/95 16(A575) 18(20D4)  
.31 improved error handling

MPU master MCH 1.820.784.25 IC 15, 17. & 18 27128

1.820.986 .20 20/88  
.21 35/88 15(8CCA) 16(6C14) 18(129B)  
.22 20/89 15(B437)27513 16(2E03) 18(D36C)  
.23 42/90  
.24 04/91 15(1C21)27513 16(891C) 18(0927)  
.25 91/10/08 same as .24, improved reset performance

MPU Audio Control 1.820.782.26 IC 16 & 18 27128

1.820.987 .20 22/87  
.21 24/88  
.22 35/88 15(4BA9) 16(6F75) 18(AA3B)  
.23 20/89 15(3D5B) 16(B135) 18(B39E)  
.24 41/90 15(0F26) 16(F145) 18(3CA0)  
.25 41/90 same as .24, improved reset performance

MPU Audio Control 1.820.

1.820.989 .20 42/90 15(0F26) 16(F145) 18(3CA0)

MPU VU panel 1.820.783.27 IC 16 ( .20 & .21) & 18 27128 also Audio Remote

1.820.988 .20 22/87  
.21 41/87  
.22 22/88  
.23 35/88 18(AE0A)  
.24 20/89 18(9FBF)  
.25 42/90 18(0C46)  
.26 42/90 same as .25, improved reset performance

Capstan Control Unit 1.820.764.28 IC 17 27128

1.820.994 .20 13/85 (2X 2764)  
.21 35/85  
.22 36/86  
.23 17/87  
.24 22/88  
.25 35/88 17(D71A)  
.26 37/89  
.27 10/92 17(3A94)

Autolocator 1.328.232.00 IC01 TBP28S42N

1.328.999 .21 50/86  
.22 29/87